

1/17

i_1	i_2					
	0	1	2	3	4	5
0	$x^{(2)}(k,0,0)$	$x^{(2)}(k,0,1)$	$x^{(2)}(k,0,2)$	$x^{(2)}(k,0,3)$	$x^{(2)}(k,0,4)$	$x^{(2)}(k,0,5)$
1	$x^{(2)}(k,1,0)$	$x^{(2)}(k,1,1)$	$x^{(2)}(k,1,2)$	$x^{(2)}(k,1,3)$	$x^{(2)}(k,1,4)$	$x^{(2)}(k,1,5)$
2	$x^{(2)}(k,2,0)$	$x^{(2)}(k,2,1)$	$x^{(2)}(k,2,2)$	$x^{(2)}(k,2,3)$	$x^{(2)}(k,2,4)$	$x^{(2)}(k,2,5)$
3	$x^{(2)}(k,3,0)$	$x^{(2)}(k,3,1)$	$x^{(2)}(k,3,2)$	$x^{(2)}(k,3,3)$	$x^{(2)}(k,3,4)$	$x^{(2)}(k,3,5)$
4	$x^{(2)}(k,4,0)$	$x^{(2)}(k,4,1)$	$x^{(2)}(k,4,2)$	$x^{(2)}(k,4,3)$	$x^{(2)}(k,4,4)$	$x^{(2)}(k,4,5)$
5	$x^{(2)}(k,5,0)$	$x^{(2)}(k,5,1)$	$x^{(2)}(k,5,2)$	$x^{(2)}(k,5,3)$	$x^{(2)}(k,5,4)$	$x^{(2)}(k,5,5)$

FIG. 1

2/17

i_1	i_2					
	0	1	2	3	4	5
0	$h^{(2)}(0,0)$	$h^{(2)}(0,1)$	$h^{(2)}(0,2)$	$h^{(2)}(0,3)$	$h^{(2)}(0,4)$	$h^{(2)}(0,5)$
1	$h^{(2)}(1,0)$	$h^{(2)}(1,1)$	$h^{(2)}(1,2)$	$h^{(2)}(1,3)$	$h^{(2)}(1,4)$	$h^{(2)}(1,5)$
2	$h^{(2)}(2,0)$	$h^{(2)}(2,1)$	$h^{(2)}(2,2)$	$h^{(2)}(2,3)$	$h^{(2)}(2,4)$	$h^{(2)}(2,5)$
3	$h^{(2)}(3,0)$	$h^{(2)}(3,1)$	$h^{(2)}(3,2)$	$h^{(2)}(3,3)$	$h^{(2)}(3,4)$	$h^{(2)}(3,5)$
4	$h^{(2)}(4,0)$	$h^{(2)}(4,1)$	$h^{(2)}(4,2)$	$h^{(2)}(4,3)$	$h^{(2)}(4,4)$	$h^{(2)}(4,5)$
5	$h^{(2)}(5,0)$	$h^{(2)}(5,1)$	$h^{(2)}(5,2)$	$h^{(2)}(5,3)$	$h^{(2)}(5,4)$	$h^{(2)}(5,5)$

FIG.2

3/17

i_1	i_2					
	0	1	2	3	4	5
0	$x^{(2)}(k,0,0)$					
1		$x^{(2)}(k,1,1)$				
2			$x^{(2)}(k,2,2)$			
3				$x^{(2)}(k,3,3)$		
4					$x^{(2)}(k,4,4)$	
5						$x^{(2)}(k,5,5)$

FIG.3

4/17

	x (k,0,1)	x (k,0,2)	x (k,0,3)	x (k,0,4)	x (k,0,5)
		x (k,1,2)	x (k,1,3)	x (k,1,4)	x (k,1,5)
			x (k,2,3)	x (k,2,4)	x (k,2,5)
				x (k,3,4)	x (k,3,5)
					x (k,4,5)

FIG.4

5/17

		i_2					
		0	1	2	3	4	5
i_1	0	$W^{(2)}(k,0,0)$	$W^{(2)}(k,0,1)$	$W^{(2)}(k,0,2)$	$W^{(2)}(k,0,3)$	$W^{(2)}(k,0,4)$	$W^{(2)}(k,0,5)$
	1	0	$W^{(2)}(k,1,1)$	$W^{(2)}(k,1,2)$	$W^{(2)}(k,1,3)$	$W^{(2)}(k,1,4)$	$W^{(2)}(k,1,5)$
	2	0	0	$W^{(2)}(k,2,2)$	$W^{(2)}(k,2,3)$	$W^{(2)}(k,2,4)$	$W^{(2)}(k,2,5)$
	3	0	0	0	$W^{(2)}(k,3,3)$	$W^{(2)}(k,3,4)$	$W^{(2)}(k,3,5)$
	4	0	0	0	0	$W^{(2)}(k,4,4)$	$W^{(2)}(k,4,5)$
	5	0	0	0	0	0	$W^{(2)}(k,5,5)$

FIG.5

6/17

		i_2					
		0	1	2	3	4	5
i_1	0	$x^{(2)}(k,0,0)$	$2x^{(2)}(k,0,1)$	$2x^{(2)}(k,0,2)$	$2x^{(2)}(k,0,3)$	$2x^{(2)}(k,0,4)$	$2x^{(2)}(k,0,5)$
	1	0	$x^{(2)}(k,1,1)$	$2x^{(2)}(k,1,2)$	$2x^{(2)}(k,1,3)$	$2x^{(2)}(k,1,4)$	$2x^{(2)}(k,1,5)$
	2	0	0	$x^{(2)}(k,2,2)$	$2x^{(2)}(k,2,3)$	$2x^{(2)}(k,2,4)$	$2x^{(2)}(k,2,5)$
	3	0	0	0	$x^{(2)}(k,3,3)$	$2x^{(2)}(k,3,4)$	$2x^{(2)}(k,3,5)$
	4	0	0	0	0	$x^{(2)}(k,4,4)$	$2x^{(2)}(k,4,5)$
	5	0	0	0	0	0	$x^{(2)}(k,5,5)$

FIG.6

7/17

i_1	i_2					
	0	1	2	3	4	5
0	$W^{(2)}(k,0,0)$	$W^{(2)}(k,0,1)$	$W^{(2)}(k,0,2)$	$W^{(2)}(k,0,3)$	$W^{(2)}(k,0,4)$	$W^{(2)}(k,0,5)$
1	0	$W^{(2)}(k-1,0,0)$	$W^{(2)}(k-1,0,1)$	$W^{(2)}(k-1,0,2)$	$W^{(2)}(k-1,0,3)$	$W^{(2)}(k-1,0,4)$
2	0	0	$W^{(2)}(k-2,0,0)$	$W^{(2)}(k-2,0,1)$	$W^{(2)}(k-2,0,2)$	$W^{(2)}(k-2,0,3)$
3	0	0	0	$W^{(2)}(k-3,0,0)$	$W^{(2)}(k-3,0,1)$	$W^{(2)}(k-3,0,2)$
4	0	0	0	0	$W^{(2)}(k-4,0,0)$	$W^{(2)}(k-4,0,1)$
5	0	0	0	0	0	$W^{(2)}(k-5,0,0)$

FIG.7

10/332036

8/17

i_1	i_2					
	0	1	2	3	4	5
0	$x^{(2)}(k,0,0)$	$2x^{(2)}(k,0,1)$	$2x^{(2)}(k,0,2)$	$2x^{(2)}(k,0,3)$	$2x^{(2)}(k,0,4)$	$2x^{(2)}(k,0,5)$
1	0	$x^{(2)}(k-1,0,0)$	$2x^{(2)}(k-1,0,1)$	$2x^{(2)}(k-1,0,2)$	$2x^{(2)}(k-1,0,3)$	$2x^{(2)}(k-1,0,4)$
2	0	0	$x^{(2)}(k-2,0,0)$	$2x^{(2)}(k-2,0,1)$	$2x^{(2)}(k-2,0,2)$	$2x^{(2)}(k-2,0,3)$
3	0	0	0	$x^{(2)}(k-3,0,0)$	$2x^{(2)}(k-3,0,1)$	$2x^{(2)}(k-3,0,2)$
4	0	0	0	0	$x^{(2)}(k-4,0,0)$	$2x^{(2)}(k-4,0,1)$
5	0	0	0	0	0	$x^{(2)}(k-5,0,0)$

FIG.8

9/17




FIG. 9

10/17




FIG.10



FIG. 11

12/17




FIG. 12

800 555 8886

13/17




FIG.13

14/17




FIG. 14

15/17




FIG. 15A




FIG. 15B

16/17




FIG. 16A




FIG. 16B

17/17




FIG.17